

APPENDIX A

Photographs



1. Upstream elevation of Bridge No. 01349



2. Downstream elevation of Bridge No. 01349



3. Downstream view from Bridge No. 01349



4. Upstream view from Bridge No. 01349



5. Typical condition of underside of deck



6. Typical condition of the truss



7. Typical condition of truss bearings



8. Typical condition of stone masonry abutments



9. Typical condition of stone masonry wingwalls



10. Typical condition of swing pier machinery



11. Typical condition of pier 2



12. Aerial view of Bridge No. 01349



13. Looking west on Route 136



14. Looking east on Route 136



15. Pier 2



16. Pier 2



17. Pier 2



18. Pier 2